

IN THE SPECIFICATION:

Please replace paragraph [0026] with the following, to correct a typographical error:

[0026] The actuators 70, 80 include cylinders 71, 81 into which the oil pressure is supplied from the compressed rods ~~57, 67~~ 47, 57. Piston rods 73, 82 slide in the cylinders 71, 81 and activate the clutch 30 by the oil pressure fed from the compressed rods 47, 57 to the cylinders 71, 81. Relief valves 75, 88 discharge oil to the accumulator 60 and reduce the inner oil pressure of the cylinders 71, 81 when the pressure inside the cylinders 71, 81 exceeds a predetermined value by a high oil pressure fed from the compressed rods 47, 57. And springs 77, 87 are respectively installed inside the cylinders 71, 81 to centralize the piston rods 73, 82 between two cylinders 41, 51.